



**FUSES:**

- T15A = L1 120VAC, Heater 1 Circuit, Delayed Fuse**
- T15A = L2 120VAC, Heater 2 Circuit, Delayed Fuse**
- T15A = L3 120VAC, Machine Circuit, Delayed Fuse**
- T15A = NUETRAL, Delayed Fuse**
- T1.25A = 15VAC, XFMR Output, Fast Acting, Mini Fuse**
- T160mA = 120VAC, XFMR Input, Fast Acting, Mini Fuse**

